



Standard Practice for Heat Fusion Joining of Polyethylene Pipe and Fittings¹

This standard is issued under the fixed designation F2620; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

^{ε1} NOTE—A1.4.3.1 was editorially revised in March 2010.

1. Scope

1.1 This practice describes procedures for making joints with polyethylene (PE) pipe and fittings by means of heat fusion joining in, but not limited to, a field environment. Other suitable heat fusion joining procedures are available from various sources including pipe and fitting manufacturers. This standard does not purport to address all possible heat fusion joining procedures, or to preclude the use of qualified procedures developed by other parties that have been proved to produce reliable heat fusion joints.

1.2 The parameters and procedures are applicable only to joining polyethylene pipe and fittings of related polymer chemistry. They are intended for PE fuel gas pipe per Specification D2513 and PE potable water, sewer and industrial pipe manufactured per Specification F714, Specification D3035, and AWWA C901 and C906. Consult with the pipe manufacturers to make sure they approve this procedure for the pipe to be joined (see Appendix X1).

NOTE 1—Information about polyethylene pipe and fittings that have related polymer chemistry is presented in Plastics Pipe Institute (PPI) TR-33 and TR-41.

1.3 Parts that are within the dimensional tolerances given in present ASTM specifications are required to produce sound joints between polyethylene pipe and fittings when using the joining techniques described in this practice.

1.4 The values stated in inch-pound units are to be regarded as the standard. The values given in parentheses are for information only.

1.5 The text of this practice references notes, footnotes, and appendixes which provide explanatory material. These notes and footnotes (excluding those in tables and figures) shall not be considered as requirements of the practice.

1.6 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.*

¹ This practice is under the jurisdiction of ASTM Committee F17 on Plastic Piping Systems and is the direct responsibility of Subcommittee F17.20 on Joining.

Current edition approved Dec. 1, 2009. Published January 2010. Originally approved in 2006. Last previous edition approved in 2006 as F2620-06. DOI: 10.1520/F2620-09E01.

2. Referenced Documents

2.1 ASTM Standards:²

D2513 Specification for Polyethylene (PE) Gas Pressure Pipe, Tubing, and Fittings

D2737 Specification for Polyethylene (PE) Plastic Tubing

D3035 Specification for Polyethylene (PE) Plastic Pipe (DR-PR) Based on Controlled Outside Diameter

D3261 Specification for Butt Heat Fusion Polyethylene (PE) Plastic Fittings for Polyethylene (PE) Plastic Pipe and Tubing

F714 Specification for Polyethylene (PE) Plastic Pipe (SDR-PR) Based on Outside Diameter

F905 Practice for Qualification of Polyethylene Saddle-Fused Joints

F1056 Specification for Socket Fusion Tools for Use in Socket Fusion Joining Polyethylene Pipe or Tubing and Fittings

2.2 PPI Documents:

TR-33 Generic Butt Fusion Joining Procedure for Field Joining of Polyethylene³

TR-41 Generic Saddle Fusion Joining Procedure for Polyethylene Gas Piping³

2.3 AWWA Documents:

AWWA C901 Standard for Polyethylene (PE) Pressure Pipe and Tubing, ½ in. (13 mm) through 3 in. (76 mm), for Water Service⁴

AWWA C906 Standard for Polyethylene (PE) Pressure Pipe and Fittings, 4 in. (100 mm) through 63 in. (1575 mm), for Water Distribution and Transmission⁴

3. Summary of Practice

3.1 The principle of heat fusion joining of polyethylene (PE) pipe is to heat two prepared surfaces to a designated temperature, then fuse them together by application of a

² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

³ Available from Plastics Pipe Institute (PPI), 105 Decker Court, Suite 825, Irving, TX 75062, <http://www.plasticpipe.org>.

⁴ Available from American Water Works Association (AWWA), 6666 W. Quincy Ave., Denver, CO 80235, <http://www.awwa.org>.

sufficient force. This force causes the melted materials to flow and mix, thereby resulting in fusion.

3.2 The heat-fusion procedures covered in this practice are socket fusion, butt fusion, and saddle fusion.

3.2.1 *Procedure 1, Socket Fusion*—The socket-fusion procedure involves simultaneously heating the outside surface of a pipe end and the inside of a fitting socket, which is sized to be smaller than the smallest outside diameter of the pipe. After the proper melt has been generated at each face to be mated, the two components are joined by inserting one component into the other. See Fig. 1. The fusion bond is formed at the interface resulting from the interference fit. The melts from the two components flow together and fuse as the joint cools. Optional alignment devices are used to hold the pipe and socket fitting in longitudinal alignment during the joining process; especially with pipe sizes IPS 3 in. (89 mm) and larger. Automated socket fusion is not addressed in this procedure.

3.2.2 *Procedure 2, Butt Fusion*—The butt-fusion procedure in its simplest form consists of heating the squared ends of two pipes, a pipe and a fitting, or two fittings, by holding them against a heated plate, removing the heater plate when the proper melt is obtained, promptly bringing the ends together, and allowing the joint to cool while maintaining the appropriate applied force.

3.2.2.1 An appropriately sized butt fusion machine is used to clamp, align and face the pipe or fitting ends and to apply the specified fusion force. See Fig. 2.

3.2.3 *Procedure 3, Saddle Fusion*—The saddle-fusion procedure involves melting the concave surface of the base of a saddle fitting, while simultaneously melting a matching pattern on the surface of the pipe, bringing the two melted surfaces together and allowing the joint to cool while maintaining the appropriate applied force. See Fig. 3.

3.2.3.1 An appropriately sized saddle fusion machine is used to clamp the pipe main and the fitting, align the parts and apply the specified fusion force.

4. Significance and Use

4.1 The procedures described in Sections 7-9 are primarily intended for (but not limited to) field joining of polyethylene (PE) pipe and fittings, using suitable equipment and appropriate environmental control procedures. When properly implemented, strong pressure/leak-tight joints are produced. When these joints are destructively tested, the failure occurs outside the fusion joined area.

4.2 Melt characteristics, average molecular weight and molecular weight distribution are influential factors in establishing suitable fusion parameters; therefore, consider the manufacturer's instructions in the use or development of a specific fusion procedure. See Annex A1.

4.3 The socket fusion, butt fusion, and saddle fusion procedures in this practice are suitable for joining PE gas pipe and fittings, PE water pipe and fittings, and PE general purpose pipes and fittings made to PE product specifications from organizations such as ASTM, AWWA, API, and ISO that are used in pressure, low pressure and non-pressure applications. For gas applications, qualification of the procedure by testing joints made using the procedure in accordance with regulations from the authority having jurisdiction are required.

5. Operator Experience

5.1 Skill and knowledge on the part of the operator are required to obtain a good quality joint. This skill and knowledge is obtained by making joints in accordance with proven procedures under the guidance of skilled operators. Evaluate operator proficiency by testing sample joints.




FIG. 1 Socket Fusion




FIG. 2 Butt Fusion




FIG. 3 Saddle Fusion

5.2 The party responsible for the joining of polyethylene pipe and fittings shall ensure that detailed procedures developed in conjunction with applicable codes and regulations and the manufacturers of the pipe, fittings, and joining equipment involved, including the safety precautions to be followed, are issued before actual joining operations begin.

6. Apparatus—General Recommendations

6.1 *Heating Tool*—Electric heating tools come in a variety of sizes that match the fusion machines capabilities. They are

designed with enough wattage and electronic control to maintain the specified heater face temperature required in this procedure. The range of the heater control shall be larger than the heating temperature specification (the typical control range is 50°F (30°C) above and below the maximum and minimum required heating tool surface temperatures. Electric heating plates maintain consistent fusion temperatures when provided with an adequate power source.

6.2 *Heating Tool Faces*—Heating tools may be made from materials such as aluminum, stainless steel, copper, or copper

alloys. Polyethylene material may stick to hot metal heating surfaces. This sticking may be minimized by applying a non-stick coating to the heating surfaces or by fitting a high-temperature, non-stick fabric over the heating surfaces. The heating plate surfaces, coated or uncoated, shall be kept clean and free of contaminants such as dirt, grease and plastic build-up, which may cause excessive sticking and create unsatisfactory joints. Most of these contaminants are removed from the hot tool surfaces using a clean, dry, oil-free lint-free cloth. Do not use synthetic fabrics which may char and stick to the fusion surface. Some pigments, such as carbon black, may stain a heating surface and probably cannot be removed; such stains will not contaminate the joint interface.

6.2.1 After a period of time in service, non-stick coatings or fabrics will deteriorate and become less effective. Deteriorated fabrics shall be replaced, and worn, scratched, or gouged non-stick coatings shall be re-coated when they lose effectiveness. Heat fusion quality may be adversely affected by deteriorated non-stick surfaces. Spray-on chemicals, such as non-stick lubricants or oils shall not be applied to heating iron surfaces as they will contaminate the joint.

6.3 *Temperature Indicator*—Heating tools shall be equipped with a thermometer or other built-in temperature indicating device. This device indicates the internal temperature of the heating iron, which is usually higher than temperature of the heating tool surfaces. Use a pyrometer, or other temperature measuring device, on the first joint of the day and periodically during the day to verify the temperature of the tool face surfaces within the pipe or fitting contact area. Select multiple checkpoints to ensure uniform surface temperature. An infrared pyrometer is calibrated by comparison to a calibrated surface pyrometer and adjusted to agree on each heating tool.

NOTE 2—A significant temperature variation, that is, cold spots, on the heating tool surfaces may indicate a faulty heating iron which may need to be serviced before it can be used.

7. Procedure 1—Socket Fusion

7.1 Apparatus:

7.1.1 *Socket Fusion Tools*—Socket fusion tools consist of a heating tool, heating tool faces, rounding clamps (cold rings), depth gage/chamfer tools, and pipe/fittings made to ASTM specifications.

7.1.2 *Heating Tool*—In order to obtain a proper melt, it is necessary for a uniform temperature to be maintained across the heating tool faces. An electrical tool shall have sufficient wattage and control to maintain the specified surface temperature of the tool faces.

7.1.3 *Heating Tool Faces*—Consisting of two parts, a male end for the interior socket surface and a female end for the exterior pipe surface. Both parts shall be made to such tolerances as to cause an interference fit. Heating tool faces are produced to Specification F1056 dimensions, and are coated with a non-stick material to keep melted pipe and fitting material from sticking to the face.

7.1.4 *Alignment Jig*—The alignment jig is an optional tool which consists of two sets of devices holding the components in alignment to each other. One set of holding devices is fixed, and the other allows longitudinal movement for making the joint.

7.1.5 *Rounding Clamps*, (cold ring) to maintain roundness of the pipe and control the depth of pipe insertion into the socket during the joining operation.

7.1.6 *Depth Gage*, for proper positioning of the rounding clamp on the pipe.

7.1.7 *Chamfering Tool*, to bevel the end of the pipe.

NOTE 3—The depth gage and chamfering tool may be combined into a single tool.

7.1.8 *Tubing Cutter*, to obtain a square end cut on the pipe.

7.1.9 *Fitting Puller*, an optional tool to assist in the removal of the fitting from the heating tool and to hold the fitting during assembly.

7.2 Procedure:

7.2.1 Attach the proper size heater faces to the heating tool, and bring the surface temperature of the tool faces to 490 to 510°F (254 to 266°C). Use a pyrometer, or other temperature measuring device, on the first joint of the day and periodically during the day to verify the temperature of the tool face surfaces within the pipe or fitting contact area. Select multiple checkpoints to ensure uniform surface temperature. Heating tool thermometers measure the internal temperature of the heating tool, which is typically higher than the surface temperature of the heating tool faces.

7.2.2 Cut the pipe end squarely, and clean the pipe end and fitting, both inside and outside, by wiping with a clean, dry, oil-free, lint-free cloth.

7.2.3 Chamfer the outside edge of the pipe end slightly and fix the rounding clamp about the pipe as determined from the depth gage. (See Note 4.)

7.2.4 Push the socket fitting onto the preheated fitting tool face first, and then push the pipe into the pipe-side tool face until the rounding clamps make contact with the heating faces.

7.2.5 Heat the pipe end and the fitting socket for the time required to obtain a proper melt. Proper melt is a function of material, time, tool temperature, and the size of the parts. Pipe and fittings of larger diameters require more time to reach the proper melt consistency than those of smaller diameters. Under-heated or overheated materials will not form a good bond. Contact the fitting manufacturer for the recommended heating times.

7.2.6 At the end of the heating time, simultaneously remove the pipe and fitting straight out from the tool, using a snap action. Immediately insert the pipe straight into the socket of the fitting so the rounding clamp is flush against the end of the fitting socket. Hold or block the joint in place until the melts of the mating surfaces have solidified. The exact cooling time depends on the size of the pipe and the material being fused.

7.2.7 Remove the rounding clamp, and inspect the melt pattern at the end of the socket for a complete impression of the rounding clamp in the melt surface. There shall be no gaps, voids, or unbonded areas. Visually inspect and compare the joint against recommended appearance guidelines (see Appendix X2).

7.2.8 Allow for extremes in weather when making field joints. Heating times, dimensional changes, etc., are affected by extreme weather conditions.

NOTE 4—Some recommend using a 50-60 grit emery or garnet cloth to roughen the outside of the pipe and inside of the fitting as a means of

minimizing any possible skin interface when making the fusion. Sandpaper is not recommended for this purpose, as it might disintegrate and contaminate the joint interface. If roughening is performed, first clean the surfaces before roughening. Clean dust and particles from the roughened surfaces afterwards by wiping with a clean, dry, oil-free cloth.

8. Procedure 2—Butt Fusion

8.1 Apparatus:

8.1.1 *Heating Tool*—The heating tool shall have sufficient area to adequately cover the ends of the size of pipe to be joined. This electrical tool shall have sufficient wattage and control to maintain the specified surface temperature of the tool faces. It shall also be equipped with heater faces that are coated with a non-stick material to prevent sticking to the pipe surface.

8.1.2 *Butt Fusion Machine*—A Butt Fusion Machine has three basic parts: (1) a stationary clamping fixture and a movable clamping fixture for aligning and holding each of the two parts to be fused. This may or may not include the power supply to operate the machine; (2) a facer for simultaneously preparing the ends of the parts to be joined (**Note 5**); and (3) appropriate inserts for clamping different pipe sizes or fitting shapes. Butt Fusion Machines are operated manually or hydraulically. Some have their own power supply and some require a separate generator. They are available in a variety of sizes to fuse pipe and tubing produced to ASTM and other industry specifications.

NOTE 5—A facer is a rotating cutting device used to square-off the pipe or fitting ends to obtain properly mating fusion surfaces. If so equipped, facing should continue until a positive mechanical stop on the butt fusion machine is reached.

8.1.3 *Pipe Support Stands*—Optional pipe support stands are used to support the pipe on both ends of the butt fusion machine to help with linear pipe alignment in the machine.

8.2 Setup:

8.2.1 Butt fusion machine setup parameters are prescribed in **Table 1**.

8.2.2 An interfacial pressure of 60 to 90 psi (0.41 to 0.62 MPa) is used to determine the force required to butt fuse the pipe components. Multiply the interfacial pressure times the pipe area to calculate the fusion force required (lb). For manually operated fusion machines, enough force should be applied to roll the bead back to the pipe surface. A torque wrench may be used to apply the proper force. Manual fusion

without a torque wrench has been used successfully by many gas utilities. For hydraulically operated fusion machines, the fusion force is divided by the total effective piston area of the movable carriage cylinders to give the theoretical butt fusion pressure in psig. The internal and external drag factors are added to this figure to obtain the actual fusion pressure in psig required by the machine. (The theoretical butt fusion pressure and the interfacial pressure are *not* the same value.) This drag pressure is found by bringing the faced pipe ends within 2 in. (50 mm) of each other and increase the pressure on the carriage until it starts moving. Back off the pressure until the carriage is barely moving and record the drag pressure in psig. Add this pressure to the theoretical butt fusion pressure to obtain the fusion machine gauge pressure in psig required for fusion.

NOTE 6—Interfacial pressure is used to determine butt fusion joining pressure settings for hydraulic butt fusion machines when joining specific pipe diameters and DR's. Interfacial pressure is *not* the gauge pressure.

8.3 Procedure:

8.3.1 Clean the inside and outside of the components (pipe or pipe and fitting) to be joined with a clean lint-free cloth. Remove all foreign matter from the piping component surfaces where they will be clamped in the butt fusion machine.

8.3.2 If applicable, place pipe support stands at both ends of the butt fusion machine and adjust the support stands to align the pipe with the fusion machine centerline. Install the pipes or fittings being joined in the stationary and movable clamps of the butt fusion machine. Leave enough pipe protruding through the clamps to allow for facing and clamp the pipe or fitting in the machine.

8.3.2.1 Take care when placing pipe or fittings in the butt fusion machine. Pipes shall be aligned before the alignment clamp is closed. Do not force the pipe into alignment by pushing it against the side of an open butt fusion machine clamp. Pipes that are freshly cut and molded fittings generally do not have toe-in, and when mated to old-cut pipe or fabricated fittings, removing toe-in can ease adjustment for high-low alignment.

8.3.3 Face the piping component ends until the facer bottoms out on the stops and is locked between the jaws to establish clean, parallel mating surfaces between the pipe/fitting ends (**Note 5**). Open the jaws and remove the facer and all shavings and debris from the facing operation with a clean, lint-free cotton cloth. Bring the pipe/fitting ends together with

TABLE 1 Butt Fusion Machine Setup Parameters

Setup Parameter		Required Condition
Manual Butt Fusion Machine	Hydraulic Butt Fusion Machine	
Set heating tool temperature and heat to specified temperature		The surface temperature of heating tool faces must be 400 to 450°F (204 to 232°C). (See X1.1 .) A pyrometer or other surface temperature measuring device should be used periodically to insure proper surface temperature of the heating tool faces.
Install inserts	Install inserts	Install inserts for the pipe OD or the fitting being fused.
Electric power supply	Electric power supply	Check field generator for adequate power supply.
Manual pressure	Set facing pressure	As required. Observe butt fusion machine manufacturer's instructions for setting facing pressure.
Manual pressure	Set heating pressure	Observe the pipe and butt fusion machine manufacturer's instructions for setting heating pressures.
Manual pressure	Set fusion joining pressure	Determine fusion joining pressure for the pipe OD and dimension ratio (DR) using 60 to 90 psi (414 to 621 kPa) interface pressure. Observe pipe and butt fusion machine manufacturer's instructions to determine the theoretical fusion joining pressure. Drag pressure is the amount of pressure required to get the carriage to move. Add this pressure to the theoretical fusion joining pressure to get the actual machine gage pressure to set.
(Drag a manual adjustment)		

minimal force. A visual inspection of this operation should verify a square face, perpendicular to the pipe centerline on each pipe end and with no detectable gap.

8.3.4 Check the pipe ends for high-low alignment and out-of-roundness. If adjustment is needed, adjust the high side down by tightening the high side clamp. Do not loosen the low side clamp or slippage may occur during fusion. Re-face the pipe or fitting ends if excessive adjustment is required (more than 180° rotation of the clamp knob) and remove any shavings from the re-facing operation with a clean, lint-free cotton cloth. The maximum high-low misalignment allowed in the butt fusion procedure is to be less than 10 % of the pipe minimum wall thickness.

8.3.5 Verify that the heater surface temperatures are in the specified temperature range 400 to 450°F (204 to 232°C). (See [Appendix X1](#).) A pyrometer or other surface temperature measuring device should be used before the first joint of the day and periodically throughout the day to insure proper temperature of the heating tool face. All pyrometers are sensitive to usage techniques. Carefully follow the manufacturer's instructions for best results. Place the heating tool in the butt fusion machine between the piping component ends and bring the pipe or fitting ends into full contact with the heating tool at fusion pressure. Briefly ensure full contact between piping component ends and the heating tool and then reduce the pressure to drag pressure but without breaking contact between the piping component ends and the heating tool. (On

larger pipe sizes, (14in. and larger) conduct a bead-up cycle where the fusion pressure must be maintained until a slight melt is observed around the circumference of the pipe or fitting before releasing pressure.) Begin the heat soak cycle by reducing the pressure to maintain contact, without force, while a bead of molten polyethylene develops between the heater and the pipe or fitting ends. Melt bead size is dependent on pipe size. See [Table 2](#) for approximate melt bead sizes.


8.3.6 When the proper bead size is observed, quickly move the piping component ends away from the heating tool, remove the heating tool and quickly inspect the pipe ends (within 3 s). (See [Appendix X1](#).)

8.3.6.1 Acceptable melt appears flat and smooth with no unmelted areas. If acceptable melt is observed, immediately bring the molten pipe ends together at the calculated fusion force determined by the pipe size and machine capability. With a manual or hydraulic machine, this will be sufficient fusion force to form a double rollback bead against the pipe wall.

8.3.6.2 Unacceptable melt appearance is any combination of a concave surface, unmelted areas, a bubbly pock-marked sandpaper-like surface or melted material sticking to heating tool surfaces. Low strength joints result from unacceptable melt appearance. Discontinue the joining procedure. Allow the component ends to cool completely and restart from [8.3.1](#). (See [Appendix X2](#).)

NOTE 7—For pipes with a wall thickness greater than 2 in. (50.80mm),

TABLE 2 Approximate Melt Bead Size



Pipe Size	"A" Approximate Melt Bead Size
1¼ in. IPS and smaller (40 mm and smaller)	1/32 to 1/16 in. (1 to 2 mm)
Greater than IPS 1¼ in. (40mm) through IPS 3 in. (90 mm)	1/16 in. (2 mm)
Greater than IPS 3 in. (90 mm) through IPS 8 in. (225 mm)	1/8 to 3/16 in. (3 to 5 mm)
Greater than IPS 8 in. (225 mm) through IPS 12 in. (315 mm)	3/16 to 1/4 in. (5 to 6 mm)
Greater than IPS 12 in. (315 mm) through IPS 24 in. (630 mm)	1/4 to 7/16 in. (6 to 11 mm)
Greater than IPS 24 in. (630 mm) through IPS 36 in. (915 mm)	7/16 in. (11 mm)
Greater than IPS 36 in. (915 mm) through IPS 65 in. (1651 mm)	9/16 in. (14 mm)

consult the pipe manufacturer. Additional heat soak time may be required.

NOTE 8—A concave melt surface is caused by unacceptable high pressure during heating.

8.3.6.3 The correct fusion pressure rolls both melt beads over so that they touch the piping component OD surfaces. Do not use excessive or insufficient force (more than or less than the fusion interfacial pressure range). If the components are brought together with excessive force, molten material may be pushed out of the joint and cold material brought into contact forming a “cold” joint. If too little force is used, voids and weak bonded areas can develop in the joint as molten material cools and contracts.

8.3.7 Hold the molten joint immobile under fusion pressure until sufficiently cooled. Cooling under pressure before removal from the butt fusion machine is important in achieving joint integrity. Maintain fusion pressure against the piping component ends for approximately 30 to 90 s per inch of pipe diameter or until the surface of the bead is cool to the touch. Avoid high stress such as pulling, installation or rough handling for an additional 30 min or more after removal from the fusion machine (only 10 minutes additional cooling time is required for IPS 1 in. and smaller pipe sizes). Do not apply internal pressure until the joint and surrounding material have reached ambient air temperature. (See [Appendix X1](#).)

NOTE 9—Pouring water or applying wet cloths to the joint to reduce cooling time is not acceptable. Applying chilled air is acceptable only as part of a controlled cooling cycle procedure where testing demonstrates that acceptable joints are produced using the controlled cooling cycle procedure.

8.3.7.1 Visually inspect and compare the joint against the butt fusion bead visual inspection acceptance guideline in [Appendix X2](#). The v-groove between the beads should not be deeper than half the bead height above the pipe surface. When butt fusing to molded fittings, the fitting-side bead may display shape irregularities such as minor indentations, deflections and non-uniform bead rollover from molder part cooling and knit lines. In such cases, visual evaluation is based mainly on the size and shape of the pipe-side bead. (See [Appendix X2](#).)

9. Procedure 3—Saddle Fusion

9.1 Apparatus:

9.1.1 *Heating Tool and Faces*—This electrical tool shall have sufficient wattage and control to maintain the specified surface temperature of the tool faces. The serrated or smooth faces are matched sets, by pipe size, of concave and convex blocks, which bolt or clamp onto a flat heating tool. The heating faces are coated with a non-stick material to prevent sticking to the pipe or fitting surfaces.

9.1.2 *Saddle Fusion Tool*—This tool clamps to the main, rounding and supporting the main for good alignment between the pipe and fitting. It holds the fitting, in correct alignment to the main. It also applies and indicates the proper force during the fusion process. A support or bolster is clamped to IPS 6 in. (168 mm) and smaller main pipe opposite the fitting installation area to support the main and assist in rounding the pipe.

9.1.3 *Optional Flexible Heat Shield*—A flexible heat resistant metal or insulated fabric pad used to help establish a melt pattern on larger mains before applying heat to the fitting.

9.2 Saddle Fusion Terminology:

9.2.1 *Initial Heat (Bead-up)*—The heating step used to develop an initial melt bead on the main pipe.

9.2.2 *Initial Heat Force (Bead-up Force)*—The force (lb) applied to establish an initial melt pattern on the main pipe. The Initial Heat Force is determined by multiplying the fitting base area (in.²) by the initial interfacial pressure (lb/in.²).

9.2.3 *Heat Soak Force*—The force (lb) applied after an initial melt pattern is established on the main pipe. The Heat Soak Force is the minimum force (essentially zero pounds) that ensures that the fitting, heater and main stay in contact with each other.

9.2.4 *Fusion Force*—The force (lb) applied to establish the fusion bond between the fitting and the pipe. The fusion Force is determined by multiplying the fitting base area (in.²) by the fusion interfacial pressure (lb/in.²).

9.2.5 *Total Heat Time*—A time that starts when the heater is placed on the main pipe and initial heat force is applied and ends when the heater is removed.

9.2.6 *Cool Time*—The time required to cool the joint to approximately 120°F (49°C). The fusion force must be maintained for 5 min on IPS 1¼ in. (42 mm) or 10 min for all other main sizes, after which the saddle fusion equipment can be removed. The joint must be allowed to cool undisturbed for an additional 30 min before tapping the main or joining to the branch saddle.

9.2.7 *Interfacial Area for Rectangular Base Fittings*—The major width times the major length of the saddle base, without taking into account the curvature of the base or sides, minus the area of the hole in the center of the base.

9.2.8 *Interfacial Area for Round Base Fittings*—The radius of the saddle base squared times π (3.1416) without taking into account the curvature of the base or sides, minus the area of the hole in the center of the base.

9.2.9 *Fitting Label*—The initial heat force, heat soak force and the fusion force will be listed on a fitting label in the lower right hand corner of the fitting for some manufacturer’s saddle fusion fittings. This will eliminate the need to calculate the fusion forces in the field (for example, 180/0/90). The label is not mandatory, therefore the heat and fusion forces need to be calculated if the label is not present.

9.3 Setup:

9.3.1 Select and install the proper heating tool faces to the heating tool based on the main size and fitting base size. Consult the pipe, fitting or equipment manufacturer’s recommendations.

9.3.2 Plug in the heating tool and bring the heating tool face surfaces to 490 to 510°F (254 to 266°C) (see [Table 3](#)). A pyrometer or other surface temperature measuring device is used to determine and periodically check the heating tool surface temperature. Heating tool thermometers measure the internal temperature of the heating tool which is typically higher than the surface temperature of the heating tool faces.

9.3.3 Install the proper clamps in the Saddle Fusion Tool for the main size to be fused. Install the proper fitting clamp for the fitting to be joined. Consult the pipe, fitting or equipment manufacturer’s recommendations.

9.4 Procedure:

TABLE 3 Generic Saddle Fusion Parameters

Heater Adapter Surface Temperature	500 ± 10°F (260 ± 6°C)
Initial Interfacial Pressure	60 ± 6 psi (4.14 ± 0.41 bar)
Heat Soak Interfacial Pressure	0 psi
Fusion Interfacial Pressure	30 ± 3 psi (2.07 ± 0.20 bar)
Total Heating Time on Main—1¼ in. IPS Pressure Main	15 s max
Total Heating Time on Main—2 in. IPS Pressure Main	25 to 35 s max
Total Heating Time on non-pressure 1¼ in. IPS, 2 in. IPS mains, and on pressure or non-pressure 3 in. IPS and larger mains.	Look for a ¼ in. (1.6 mm) bead around the fitting base

9.4.1 Preparation:

9.4.1.1 Install the Saddle Fusion Tool on the main according to the manufacturer's instructions. The tool should be centered over a clean, dry location where the fitting will be fused. Secure the tool to the main. A main bolster or support is recommended under the pipe on IPS 6 in. (168 mm) and smaller main pipe sizes.

9.4.1.2 Abrade or scrape the surface of the main, where the fitting will be joined, approximately 0.007 in. (.178mm) deep to remove any oxidation or contamination. This can be done before or after the Tool is attached to the main. The abraded/scraped area must be larger than the area covered by the fitting base. It is important that the pipe surface be free from any type of contaminants that may be spread before the scraping or abrading process begins. Marks can be made on the outer surface of the pipe to aid in visual indication of abrading/scraping coverage, however the marks should not be made with a "grease pencil" or other marker that will leave a contaminate behind. After abrading/scraping, brush residue away with a clean, dry cloth.

9.4.1.3 If the fitting is not protected in a clean plastic bag, abrade the fusion surface of the fitting with 50 to 60 grit utility cloth; remove all dust and residue. Insert the fitting in the Saddle Fusion Tool loosely. Using the Saddle Fusion Tool, move the fitting base against the main pipe and apply about 100 lbf to seat the fitting. Secure the fitting in the Saddle Fusion Tool.

9.4.2 Heating Procedure for Small Fittings (<2 in. IPS) (see Table 3):

9.4.2.1 Place the heating tool on the main centered beneath the fitting base. Immediately move the fitting against the heater faces, apply the Initial Heat Force (see fitting label), and start the heat time. Apply the Initial Heat Force until melt is first observed on the crown of the pipe main (Initial Heat is the term used to describe the initial heating (bead-up) step to develop a melt bead on the main pipe and usually is 3 to 5 s) and then reduce the force to the Heat Soak Force (Bead-up force) (see fitting label). Maintain the Heat Soak Force until the Total Heat Time is complete. Total Heat Time ends:

(1) When the Total Heating Time expires for a pressurized IPS 1¼ in. (42 mm) or IPS 2 in. (63 mm) main, or

(2) When a melt bead of about ¼ in. (2 mm) is visible all around the fitting base for a IPS 1¼ in. (42 mm) or IPS 2 in. (63 mm) non-pressurized main, or a larger pressurized or non-pressurized main, (see Table 3).

9.4.2.2 At the end of the Total Heat Time, remove the fitting from the heater and the heater from the main with a quick snapping action. Quickly check for a complete and even melt pattern on the pipe main and fitting heated surfaces (no unheated areas).

9.4.3 Heating Procedure for Large Fittings (>IPS 3 in.) and Large Mains (>IPS 6 in.) (see Table 3):

9.4.3.1 Place the heating tool on the main centered beneath the fitting base, and then place the Flexible Heat Shield between the heating tool and the fitting base. (This step usually requires an assistant to handle the Flexible Heat Shield).

9.4.3.2 Move the fitting against the Flexible Heat Shield, apply Initial Heat Force, and observe melt bead formation on the main all around the heating tool faces. When a melt bead is first visible on the main all around the heating tool faces, in a quick continuous motion, release the Initial Heat Force, raise the fitting slightly, remove the Flexible Heat Shield, move the fitting against the heating tool face, apply Initial Heat Force and start the heat time. When a melt bead is first visible all around the fitting base (usually about 3 to 5 s) immediately reduce applied force to the Heat Soak Force (usually zero). Maintain the Heat Soak Force until the Table 3 Total Heat Time ends.

NOTE 10—During heating, hold the heating tool in position by lightly supporting the heating tool handle. If not supported, the heating tool can slip out of position or displace the main or fitting melt and result in a poor joint.

9.4.3.3 At the end of the Total Heat Time, remove the fitting from the heater and the heater from the main with a quick snapping action. Quickly check for a complete and even melt pattern on the pipe main and fitting heated surfaces (no unheated areas). A mirror may be needed to check the bottom of the fitting.

9.4.4 Fusion and Cooling (see Table 3):

9.4.4.1 Whether or not the melt patterns are satisfactory, press the fitting onto the main pipe very quickly (within 3 s) after removing the heater and apply the Fusion Force (see the fitting label). Maintain the Fusion Force on the assembly for 5 min on IPS 1¼ in. (42 mm) and for 10 min on all larger sizes, after which the saddle fusion equipment may be removed. (Fusion Force adjustment may be required during Cool Time, but never reduce the Fusion Force during cooling.)

9.4.4.2 Cool the assembly for an additional 30 min before rough handling, branch joining or tapping the main. (If the melt patterns were not satisfactory or if the fusion bead is unacceptable, cut off the saddle fitting above the base to prevent use, relocate to a new section of main, and make a new saddle fusion using a new fitting.)

NOTE 11—These procedures are based on tests conducted under controlled ambient temperature conditions. Environmental conditions on a job site could affect heating and cooling times. Regardless of job site conditions or ambient temperature, the prescribed heating tool temperature is required. Do not increase or decrease the heating tool temperature. When saddle fittings are fused to pipes that are under pressure, it is important that the surface melt be obtained quickly without too much heat



penetration without exceeding the time guidelines in Table 3. Otherwise, too much heat penetration could result in pipe rupture from internal pressure.

9.5 Visual Inspection:

9.5.1 Visually inspect and compare the joint against visual inspection guidelines. There shall be three beads, a melt bead around the fitting base, a bead on the main from the edge of the heating tool, and a main pipe melt bead. The fitting and pipe melt beads should be rounded and about 1/8 in. (3 mm) wide all around the fitting base. The heating tool edge bead should be visible all around the fitting base, but may be separate from the main pipe melt bead.

9.5.2 The saddle fusion joint is unacceptable for use if visual bead appearance is unacceptable or if the melted surfaces were unacceptable. To prevent use, cut the fitting off at or just above the base. (See Appendix X2.)

NOTE 12—Look in the lower right hand corner of the fitting label for the forces required for that fitting in pounds force (Initial Heat Force/Heat Soak Force/Fusion Force) (for example, 180/0/90).

10. Keywords

10.1 butt fusion; fitting; heat fusion; joining; pipe; polyethylene; polyolefin; saddle fusion; socket fusion

ANNEX

(Mandatory Information)

A1. COLD WEATHER PROCEDURES

A1.1 Cold Weather Handling:

A1.1.1 Pipe shall be inspected for damage. Polyolefin Polyethylene pipes have reduced impact resistance in sub-freezing conditions. Avoid dropping pipe in sub-freezing conditions. When handling coiled pipe at temperatures below 40°F (4.44°C), it is helpful to uncoil the pipe prior to installation and let it straighten out. Gradually uncoil the pipe and cover it with dirt at intervals to keep it from recoiling. Always use caution when cutting the straps on coils of pipe because the outside end of a coil may spring out when the strapping is removed.

A1.2 Preparation for Socket, Saddle, and Butt Fusion Joining:

A1.2.1 *Wind and Precipitation*—The heating tool shall be shielded in an insulated container to prevent excessive heat loss. Shield the pipe fusion area and fusion tools from wind, snow, blowing dust, and rain by using a canopy or similar device.

A1.2.2 *Pipe and Fitting Surface Preparation*—The pipe and fitting surfaces to be “joined” or held in clamps shall be dry and clean and free of ice, frost, snow, dirt, and other contamination. Regular procedures for preparation of surfaces to be joined, such as facing for butt fusion and roughening for saddle fusion shall be emphasized. After preparation, the surfaces shall be protected from contamination until joined. Contamination of the area to be fused will likely cause incomplete fusion. Frost and ice on the surfaces of the pipe to be clamped in either a cold ring or alignment jigs may cause slippage during fusion. Inspect coiled pipe to see if it has flattened during storage, which could cause incomplete melt pattern or poor fusion. It may be necessary to remove several inches at the pipe ends to eliminate such distortion. Pipe may have a slight toe-in or reduced diameter for several inches at the end of the pipe. The toe-in may need to be removed before butt fusing to a freshly cut pipe end, or to a fitting.

A1.2.3 *Heating*—Work quickly once pipe and fitting have been separated from the heating tool, so that melt heat loss is minimized, but still take time (no more than 3 s) to inspect both

melt patterns. Keep the heater dry at all times. Check the temperature of the heating tool regularly with a pyrometer or other surface temperature measuring device. Keep the heating tool in an insulated container between fusions. Do not increase heating tool temperature above the specified temperature setting. Gas-fired heating tools are used only in above freezing conditions.

A1.3 Socket Fusion:

A1.3.1 *Pipe Outside Diameter*—Pipe outside diameter contracts when cold. This results in loose or slipping cold rings. For best results, clamp one cold ring in its normal position adjacent to the depth gage. Place shim material (that is, piece of paper or rag, etc.) around the inside diameter of a second rounding ring and clamp this cold ring directly behind the first cold ring to prevent slippage. The first cold ring allows the pipe adjacent to the heated pipe to expand to its normal diameter during the heating cycle.

A1.3.2 *Fitting Condition*—If possible, store socket fittings at a warm temperature, such as in a truck cab, prior to use. This will make it easier to place the fitting on the heating tool because fittings contract when cold.

A1.3.3 *Heating*—At colder temperatures the pipe and fitting contract, thus the pipe slips more easily into the heating tool. At very cold outdoor temperatures (particularly with IPS 2, 3, and 4-in. pipe), the pipe may barely contact the heating surface. Longer heating cycles are used so that the pipe first expands (from tool heat) to properly contact the heating tool, then develops complete melt. The length of cycle necessary to obtain a complete melt pattern will depend not only on the outdoor (pipe) temperature but wind conditions and operator variation. Avoid cycles in excess of that required to achieve a good melt pattern. To determine the proper cycle time for any particular condition, make a melt pattern on a scrap piece of pipe, using the heating cycle as instructed by the pipe manufacturer. If the pattern is incomplete (be sure rounding rings are being used), try a 3 s longer cycle on a fresh (cold) end of pipe. If the melt pattern is still not completely around the pipe end,

add an additional 3 s and repeat the procedure. Completeness of melt pattern is the key. Keep the heater dry at all times. Check the temperature of the heating tool regularly and keep the heating tool in an insulated container between fusions.

A1.4 Butt Fusion:

A1.4.1 Joining:

A1.4.1.1 The fusion operator shall be aware of ambient weather conditions during the butt fusion of polyethylene pipe and fittings and be ready and capable to make adjustments to the fusion procedure if ambient weather conditions change significantly.

A1.4.1.2 The qualified fusion procedure shall provide suitable measures for adjustment of fusion parameters, in particular the heating cycle time, when the ambient temperature changes or during windy conditions. When the ambient temperature becomes colder, it will require a longer heating time to develop the melt beads in the Bead-Up and Heat Soak cycles. The pipe wall thickness and pipe diameter are primary factors to consider when determining the necessary heating cycle time.

A1.4.1.3 The modifications to the fusion procedure require validation through the production of test fusions and their assessment by comparison to visual guidelines and bend testing.

A1.4.1.4 The specified heating plate temperature range shall not be exceeded to accommodate cold weather conditions.

A1.4.1.5 The fusion pressure must be maintained until a slight melt is observed around the circumference of the pipe or fitting before releasing pressure for the heat soak cycle.

NOTE A1.1—Check for pipe slippage in the fusion machine in cold weather applications. The pipe is stiffer in cold temperatures and the OD of the pipe will shrink slightly, increasing the potential for slippage in the jaws.

A1.4.1.6 Do not apply additional pressure during the heat soak cycle to accommodate cold weather conditions.

A1.4.1.7 The melt beads formed against the heater surface during the heating cycle shall be in accordance with Table 2. It is critical that the melt bead sizes specified in Table 2 be achieved.

A1.4.1.8 When the specified melt bead size has been achieved, the pipe and heater shall be separated in a rapid,

snap-like motion. The melted surfaces shall then be joined as soon as possible so as to minimize cooling of the melted pipe ends (See Fig. 4).

A1.4.2 Assessment – Inspection assessment guidelines for fusion joints that are made under cold weather conditions are the same as for fusion joints made at warmer ambient temperatures. Key concerns affecting the quality of cold weather fusion joints are incorrect heating time and application of pressure during heating soak cycle and moisture contamination that could generate a weak fusion joint. Therefore strict adherence to the butt fusion guidelines and adequate butt fusion process controls are the primary means to minimize this probability.

A1.4.2.1 Visual assessment of the finished bead is critical, since signs of incorrect heating, facing or joining force may be evident on the fusion bead. Correct shape of the finished bead, degree of bead rollover to the pipe surface and depth of the v-groove are key indicators.

A1.4.3 Joining in Adverse Weather:

A1.4.3.1 Cold Ambient Temperatures Below 32°F (0°C)—Butt, Saddle or Socket, Fusion is generally not recommended below -4°F (-20°C) without special provisions such as a portable shelter or trailer or other suitable protective measures with auxiliary heating. When making a butt fusion joint with the ambient temperature is below 3°F (-16°C), the pipe ends shall be pre-heated using a heating blanket or warm air device to elevate the pipe temperature to improve the heating cycle starting condition. With pipe mounted in the fusion machine, an alternate method of pre-heating is to stop the pipe ends within .25-.50 inches (6.4-12.7mm) of the heater plate face to allow the pipe ends to warm for 30 seconds to 2 minutes, depending on the pipe size and wall thickness. The use of direct application open flame devices, such as torches, for heating polyethylene pipe is prohibited due to the lack of adequate heating control and possibility of damage to the pipe ends. When fusing pipe under adverse cold weather or in windy field conditions with blowing dust is required, the provision of portable shelters or trailers with heating should be considered and are recommended to provide more consistent and acceptable working conditions. When fusing coiled pipe when the ambient temperature is below 32°F (0°C), it may be required to remove an end section of pipe from the coil and butt fuse on a straight section of pipe to enable correct pipe alignment.




FIG. 4 Butt Fusion Bead Dimensional Guideline

Completed joints shall be allowed to cool to ambient temperature before any stress is applied.

A1.4.3.2 *Wind*—Exposure of the fusion heater plate and pipe to wind can result in unacceptable temperature variations during butt fusions and possible joint contamination. When extreme wind conditions exist, the provision of a suitable shelter is required to protect the pipe and fusion heater plate to ensure a more consistent environment is provided. Wind conditions can develop through the pipe bore and cause unacceptable temperature variations during the heating process. Therefore, open pipe ends may require plugs or covers to prevent this condition. Note: Although wind conditions, during cold weather butt fusion, are the primary concern, wind conditions can affect butt fusion quality at all ambient temperatures by chilling the heated pipe surfaces during the heat soak cycle. This increases the heat soak time to obtain the bead size against the heater surface.

A1.5 *Saddle Fusion*:

A1.5.1 *Surface Preparations*—Regular procedures for roughening the surfaces to be fused on the pipe and the fitting shall be emphasized. After the surfaces have been prepared, particular care shall be taken to protect against contamination.

A1.5.2 *Heating Time*—Make a trial melt pattern on a scrap piece of pipe. A clean, dry piece of wood is used to push the heating tool against the pipe. If the melt pattern is incomplete, add 3 s to the cycle time and make another trial melt pattern on another section of cold pipe. If the pattern is still incomplete, continue 3 s additions on a fresh section of cold pipe until a complete melt pattern is attained. Use this heating cycle for fusions during prevailing conditions. Regardless of the weather or the type of tools used, the important point to remember is that complete and even melt must occur on the fitting and the pipe in order to produce a good fusion joint. This requires pipe preparation to make it clean, straight, round, and well supported.

APPENDIXES

(Nonmandatory Information)

X1. JOINING

X1.1 *Parameters and Procedures*—These parameters and procedures in this practice are approved by the majority of pipe manufacturers for the majority of the solid wall polyethylene pipe materials on the market today. Consult with the pipe manufacturer to make sure they approve this procedure for the pipe to be joined. Other specific parameters and procedures, such as heater temperature variations, have been developed, tested and approved by some municipalities, utilities, and end users. They are not covered in this specification.

X1.2 *Quality Assurance Recommendations*—It is recommended that the following steps be followed to help insure quality fusion joints.

X1.2.1 Make sure the equipment or tooling used to make the fusion joints is in good working order and conforms to the equipment manufacturer's quality assurance guidelines.

X1.2.2 Make sure the operator of the equipment or tooling to be used has had the proper training in the operation of that equipment.

X1.2.3 If possible, use a datalogging device with hydraulic joining equipment to record the critical fusion parameters of pressure, temperature and time for each joint.

X1.2.4 Visually inspect each joint and compare the data-logged records to this approved standard before burying the pipe. (See [Appendix X2](#) for visual guidelines.)

X1.3 *Heating Polyethylene (PE) in a Hazardous Environment*—Electrically powered heat fusion tools and equipment are usually not explosion proof. When performing heat fusion in a potentially combustible atmosphere such as in an excavation where gas is present, all electrically powered tools and equipment that will be used in the combustible

atmosphere shall be disconnected from the electrical power source and operated manually to prevent explosion and fire. For the heating tool, this requires bringing the heating tool up approximately 25°F (14°C) above the recommended maximum surface temperature in a safe area, then disconnecting it from electrical power immediately before use.

X1.4 *Butt Fusion of Unlike Wall Thicknesses*—The butt fusion procedure in this practice is based on joining piping components (pipes and fittings) made from compatible polyethylene compounds having the same outside diameter and wall thickness (PR) per ASTM or other industry product specifications. In some cases, butt fusion joining of pipes and fittings that have the same outside diameter but unlike wall thickness (different by one standard DR or more) is possible. The quality of butt fusion joints made between pipes of unlike wall thickness is highly dependent on the performance properties of the polyethylene compound used for the pipes or fittings being joined. Consult the pipe or fitting manufacturer for applicable butt fusion procedures for components with dissimilar wall thicknesses.

X1.5 *Butt Fusion of Coiled Pipe*—Coiled pipe is available in sizes up to 6 in. IPS. Coiling may leave a set in some pipe sizes that must be addressed in the preparation of the butt fusion process. There are several ways to address this situation:

X1.5.1 Straighten and re-round coiled pipe before the butt fusion process. (Specification [D2513](#) requires field re-rounding of coiled pipe before joining pipe sizes larger than 3 in. IPS.)

X1.5.2 If there is still a curvature present, install the pipe ends in the machine in an "S" configuration with the print lines

approximately 180° apart in order to help gain proper alignment and help produce a straight joint. See Fig. X2.15.

X1.5.3 If there is still a curvature present, another option would be to install a straight piece of pipe between the two coiled pipes.


NOTE X1.1—Every effort should be made to make the joint perpendicular to the axis of the pipe. Visually mitered (angled, off-set) joints should be cut out and re-fused (see appearance guidelines in [Appendix X2](#)).

X2. HEAT FUSION VISUAL APPEARANCE GUIDELINE




Melt bead flattened by cold ring.
No gaps or voids.
Good alignment between pipe and fitting.

FIG. X2.1 Acceptable Visual Appearance Socket Fusion




Excessive heating.

FIG. X2.2 Unacceptable Visual Appearance Socket Fusion



Melt bead not flattened against the fitting/cold ring.
Improper insertion depth; no cold ring.
Excessive heating.

FIG. X2.3 Unacceptable Visual Appearance Socket Fusion



Misalignment.

FIG. X2.4 Unacceptable Visual Appearance Socket Fusion




FIG. X2.5 Butt Fusion Bead Visual Acceptance Guideline



Proper double roll-back bead.
Proper alignment.

FIG. X2.6 Acceptable Visual Appearance Butt Fusion



Incomplete face-off.

FIG. X2.7 Unacceptable Visual Appearance Butt Fusion



Unacceptable concave melt appearance after heating.
Possible over-pressurization during the heat cycle.

FIG. X2.8 Unacceptable Visual Appearance Butt Fusion



Improper “high-low” pipe alignment.
Visually mitered joint.

FIG. X2.9 Unacceptable Visual Appearance Butt Fusion



Improper alignment in fusion machine—mitered joint.

FIG. X2.10 Unacceptable Visual Appearance Butt Fusion



Contamination in joint.

FIG. X2.11 Unacceptable Visual Appearance Butt Fusion



Proper alignment, force and melt.
Proper surface preparation.

FIG. X2.12 Acceptable Visual Appearance Saddle Fusion Joint



Improper alignment.
Fitting offset from melt pattern.

FIG. X2.13 Unacceptable Visual Appearance Saddle Fusion Joint



Over-melt of fitting and main.
Possible over-pressurization of fitting on main.

FIG. X2.14 Unacceptable Visual Appearance Saddle Fusion Joint



Under-melt of fitting and main.
Fitting offset from melt pattern.
Possible under-pressurization of fitting on main.

FIG. X2.15 Unacceptable Visual Appearance Saddle Fusion Joint




FIG. X2.16 Coiled Pipe Installation in Fusion Machine

X3. DETERMINING SADDLE FUSION FORCE IF LABEL IS NOT PRESENT

X3.1 When the saddle fusion fitting does not have a label to show the initial heat force (IHF) and the fusion force (FF), use the following formulas to determine the forces required.

$$IHF = L \times W - (0.785 \times d^2) \times 60 \quad (X3.1)$$

$$IHF = 0.785 \times (D^2 - d^2) \times 60 \quad (X3.2)$$

X3.2 Determining IHF and FF:

X3.2.1 IHF is determined by multiplying the area of the saddle fitting base by 60 psi, the initial interface pressure. For rectangular base saddle fittings, the fusion area is the base length times the base width less the area of the outlet hole. Base curvature and corner radii are ignored. For round base saddle fittings, the fusion area is the area of the base outside diameter less the area of the outlet hole. Base curvature is ignored.

where:

IHF = initial heat force, lb,
L = rectangular base length, in.,
W = rectangular base width, in.,
d = outlet hole inside diameter, in., and
D = round base outside diameter, in.

X3.2.2 *FF* is one-half of *IHF*:

$$FF = \frac{IHF}{2} \quad (X3.3)$$

X4. BEND BACK TESTING OF FUSED JOINTS

X4.1 It is possible to evaluate sample joints in order to verify the skill and knowledge of the fusion operator. Cut joints into straps, (see Fig. X2.15) and visually examine and test for bond continuity and strength. Bending, peeling, and elongation tests are useful for this purpose. These tests are generally conducted on smaller pipe sizes. For butt fusion test straps, limit the wall thickness of the pipe to 1 in. (25mm) to prevent possible injury in conducting the test. Visually inspect the cut joint for any indications of voids, gaps, misalignment of surfaces that have not been properly bonded. Bend each sample at the fusion joint with the inside of the pipe facing out until the ends touch. The inside bend radius should be less than the

minimum wall thickness of the pipe. In order to successfully complete the bend back, a vise may be needed. The sample must be free of cracks and separations within the fusion joint location. If failure does occur at the weld in any of the samples, then the fusion procedure should be reviewed and corrected. After correction, another sample fusion joint should be made per the new procedure and re-tested. Bend testing of pipes with a wall thickness greater than 1 in. (25mm) could be hazardous and should be done with an approved bending fixture that supports and contains the pipe during the test or with another approved procedure.




FIG. X4.1 Bent Strap Test Specimen

ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.

This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or service@astm.org (e-mail); or through the ASTM website (www.astm.org). Permission rights to photocopy the standard may also be secured from the ASTM website (www.astm.org/COPYRIGHT/).