


# Chapter 9

## Meshing


- 9.1 Pneumatic Fingers
- 9.2 Cover of Pressure Cylinder
- 9.3 Convergence Study of 3D Solid Elements
- 9.4 Review

# Section 9.1

## Pneumatic Fingers




### Problem Description



## Techniques/Concepts

- Mesh Metric: Skewness
- Hex Dominant Method
- Sweep Method
- MultiZone Method
- Section View





# Section 9.2

## Cover of Pressure Cylinder

### Techniques/Concepts


- Patch Conforming Method
- Patch Independent Method







# Section 9.3

## Convergence Study of 3D Solid Elements


### Problem Description




# Element Shapes





# Lower-Order Elements





# Higher-Order Elements





# Hexahedra




# Tetrahedra



# Parallel Prisms



# Perpendicular Prisms



## Guidelines

- Never use lower-order tetrahedra/triangles.
- Higher-order tetrahedra/triangles can be as good as other elements as long as the mesh is fine enough. In cases of coarse mesh, however, they perform poorly and are not recommended.
- Lower-order prisms are not recommended.
- Lower-order hexahedra/quadrilaterals can be used, but they are not as efficient as their higher-order counterparts.
- Higher-order hexahedra, prisms, and quadrilaterals are among the most efficient elements so far we have discussed. Mesh your models with these elements whenever possible. If that is not possible, then at least try to achieve a higher-order hexahedra-dominant or quadrilateral-dominant mesh.