ERRATA SHEET

AWS D15.2:2003, *Recommended Practices for the Welding of Rails and Related Rail Components for Use by Rail Vehicles*

Page ix, Table of Contents, change caption to Figure 2 to read "Typical Skip Welding Repair".

Page 5, Figure 2, delete "5 in. (125mm)" and change caption to read "Typical Skip Welding Repair".