


IRON - CARBON/CEMENTITE PHASE DIAGRAM



The heat colors on this chart are approximate reproductions of colors observed on a bar of steel as seen through a furnace peephole. They should be viewed under average fluorescent room lighting conditions. ~500 Lux.



The Materials Information Society

Compiled by G.E. Welsch, Case Western Reserve University

Phase diagram from Binary Alloy Phase Diagrams, Second Edition, edited by T.B. Massalski, H. Okamoto, P.R. Subramanian, L. Kacprzak

Materials Park, Ohio 44073-0002
Call 440-338-5151 Fax: 440-338-4634

Copyright © 1994 by ASM International

Microstructures courtesy of G. Vander Voort, Carpenter Technology Corporation, and A. Benscoter, Lehigh University