

## جدول پرمصرف ترین دستورات وکلیدهای میانبر در سالیدورک

### File Shortcuts

|          |                                          |
|----------|------------------------------------------|
| Ctrl + N | New                                      |
| Ctrl + O | Open                                     |
| Ctrl + D | Makes new drawing from part or assembly  |
| Ctrl + A | Makes new assembly from part or assembly |
| Ctrl + S | Save                                     |

### Edit Shortcuts

|          |                      |
|----------|----------------------|
| Ctrl + Z | Undo                 |
| Ctrl + Y | Redo                 |
| Enter    | Repeats last command |
| Ctrl + X | Cut                  |
| Ctrl + C | Copy                 |
| Ctrl + V | Paste                |
| Delete   | Delete               |
| Ctrl + B | Rebuilds             |

|                    |                                                 |
|--------------------|-------------------------------------------------|
| Ctrl + Q           | Forced rebuild                                  |
| Ctrl + R           | Redraws screen                                  |
| S                  | Opens shortcut bar                              |
| Ctrl + click items | Selects multiple items                          |
| Shift + drag       | Moves item                                      |
|                    | View Shortcuts                                  |
| Arrow keys         | Rotates model                                   |
| Ctrl + arrow keys  | Pans model                                      |
| Ctrl + R           | Redraws the screen                              |
| Spacebar           | Orientation                                     |
| F                  | Zooms to fit                                    |
| Shift + Z          | Zooms in                                        |
| Z                  | Zooms out                                       |
| Alt + arrow keys   | Rotates the model parallel to the viewing plane |
| Shift + arrow keys | Rotates the model 90°                           |

|                          |                                                                                                               |
|--------------------------|---------------------------------------------------------------------------------------------------------------|
| Alt + middle mouse wheel | Shows a section view when using the magnifying glass                                                          |
| G                        | Magnifying Glass                                                                                              |
| Dimension shortcuts      |                                                                                                               |
| Alt + click              | Turns off automatic alignment when you place dimensions and annotations                                       |
| Alt + drag               | Moves an annotation independently from the group in which it is contained                                     |
| Ctrl + drag              | Creates additional leaders on a note when you Ctrl + drag a leader's arrowhead                                |
| Shift + click            | Snaps a dimension to the max or min location when dimensioning arcs and circles with the Smart Dimension tool |
| Sketching shortcuts      |                                                                                                               |
| Ctrl + drag              | Suppresses inference lines when dragging an endpoint                                                          |
| Pressing Ctrl            | while sketching turns off automatic sketch relations                                                          |
| Shift + click            | Turns on snapping                                                                                             |

Shift + drag      When sketching a line, the line snaps to specific lengths

---

Tab      Changes the XYZ plane when sketching in a 3D sketch

---

Assembly shortcuts Alt + drag

- Mates. Creates a SmartMate when you Alt + drag a component
- Reordering components. When moving a component in the FeatureManager design tree, ensures that the component remains at the same level in the tree and prevents it from being moved into a subassembly
- Alt + Ctrl drag      Copies the component and creates a SmartMate
- Ctrl + drag      Copies a component when you Ctrl + drag it
- Selection. In an assembly with preselected components, inverts the selection when you Ctrl + drag a selection box
- Toolbox. Creates a part instead of a configuration when you drag a Toolbox component into an assembly
- Tab      Hide/Show. Hides all components below the pointer

- While Inserting a Component. Rotates the component 90°

Shift + Tab · Hide/Show. Shows all components below the pointer

- While Inserting a Component. Rotates the component -90°

Ctrl + Shift + TabTemporarily displays all hidden components as transparent and lets you select which ones to show